



**REPORT OF THIRD PARTY INSPECTION**

**Order No.:** 7482583311

**Applicant:** Sailuoke Fluid Equipment Inc.

**Address:** 156 Tongxin Road, Chongzhou Economic Zone,  
611230, Chengdu City, Sichuan, P.R. China

**Commodity description:** Fittings

**Quantity:** XXX

**Manufacturer:** as same as applicant

**Contact Person:** Mr. Song

**Inspection Place:** as same as the address of applicant

**Inspection Date:** December 17, 2025 ~ January 03, 2026

**Inspector:** Mr. Xu Zhujun/Mr. Zhang Xulie

**Product Serial Number:** XXXX

**TÜV SÜD Certification and Testing (China) Co., Ltd. Shanghai Branch**

Floor 3-13, No.151, Heng Tong Road,  
Shanghai, P. R. China  
Tel.: +86(0) 21 6141 0123  
Fax: +86(0) 21 6140 8600  
Internet: www.tuvsud.cn  
Email: Zhujun.xu@tuvsud.com

The Report may only be quoted in full. Any use for advertising purposes must be granted in writing.

The test results refer exclusively to the units under test.





- Nature of Inspection:**
1. Over pressure
  2. External leakage test
  3. Corrosion resistance test
  4. Temperature cycle test
  5. Vibration resistance test
- 

This is to report that we, TÜV SÜD Certification and Testing (China) Co., Ltd. Shanghai Branch at the request of Sailuoke Fluid Equipment Inc. conducted the following inspections and witnessing of test according to relevant drawing provided by the manufacturer.

#### **1. Over pressure**

The over pressure test is performed on the lab of Sailuoke Fluid Equipment Inc. the detail is showed in the attached-1. The result of test is conform to the request of annex 5A over pressure test of ECE R 110.

#### **2. External leakage test**

The external/internal leakage test is performed on the lab of Sailuoke Fluid Equipment Inc. the detail is showed in the attached -2. The result of test is conform to the request of annex 5B External leakage test of ECE R 110.

#### **3. Corrosion resistance test**

The corrosion resistance test is performed on the lab of Sailuoke Fluid Equipment Inc. the detail is showed in the attached-3. The result of test is conform to the request of annex 5E Corrosion resistance test of ECE R 110.

#### **4. Temperature cycle test**

The temperature cycle test is performed on the lab of Sailuoke Fluid Equipment Inc. the detail is showed in the attached-4. The result of test is conform to the request of annex 5H Temperature cycle test of ECE R 110.

#### **5. Vibration resistance test**

The vibration resistance test is performed on the lab of Sailuoke Fluid Equipment Inc. the detail is showed in the attached-5. The result of test is conform to the request of annex 5N Vibration resistance test of ECE R 110.





Note: All original reports above maybe obtained in the manufacturer.

Inspector Signature:

A handwritten signature in blue ink, appearing to read 'Zhu Jun'.

Inspector: Zhujun XU/Xulie ZHANG

Date of Issue: 2026-02-04

TÜV SÜD Certification and Testing (China) Co., Ltd. Shanghai Branch

Click or tap here to enter text



Attached 1~5 -- ECE R110 test reports

Attached 6 – Test equipment data sheet

Attached 7—Drawings list for test sampled fittings.